



## **YASS VALLEY COUNCIL**

### **ARBORIST REPORT – 110 Rossi Street YASS**

#### **MICHAEL REEVES LANDSCAPE ARCHITECT**

23 May 2025

#### **Author Qualifications**

I am Michael David REEVES, MMAMP Pty Ltd trading as Michael Reeves Landscape Architects, 35 Darke Street TORRENS ACT 2607.

Phone Number 02 6290 1728 and 0413 403 483      Email [mreeves1@bigpond.net.au](mailto:mreeves1@bigpond.net.au)

I am the Principal of Michael Reeves Landscape Architect. Michael Reeves Landscape Architect is a firm specialising in the provision of professional arborist and landscape architect related services.

I have prepared this Arborist Report.

I have worked in Canberra and New South Wales in private practice and landscape construction as a professional Registered Landscape Architect and consultant arborist for forty years.

I am a Fellow Member of the Australian Institute of Landscape Architects. I have been a Registered Landscape Architect #486 since January 7, 1990.

As Principal of Michael Reeves Landscape Architect, I am responsible for and authorise release of arborist and landscape architecture reports and services.

Any opinions expressed by me in this Arborist Report are my own opinions. They have not been prescribed or prepared by any other person.

#### **Application**

Yass Valley Council requested an arborist inspection of a Melia azedarach (White Cedar) on the Rossi Street nature strip adjacent to 110 Rossi Street, Yass.

### Tree Description / Inspection

The site is the grassed nature strip of Rossi Street Yass.

The tree is located adjacent to 110 Rossi Street.

The tree is a *Melia azedarach* (White Cedar). 6m Height and Crown Spread of 12m and Diameter Breast Height of 1.0m.

Tree has experienced continual pruning to remove the tree canopy from adjacent to the power line conductors. The tree is adjacent to the power pole (3m).

The tree is mature with overextended branch structure.

The tree species at maturity can expect a height of 20m. This places the tree in continual conflict with the power supply and necessitates continual pruning.

This tree species is not appropriate for this location.

The elongated and overextended main branches of this tree and the potential for splitting at the attachments on the trunk base contribute to the MODERATE risk assessment for this tree.

The likelihood of failure is probable. Recommendation is for removal at the earliest opportunity and replacement with a tree species appropriate for the location and powerline constraints.



Should you require further information, or clarification of any of this report, please call me.

Regards

A handwritten signature in blue ink, appearing to read "M. Reeves". The signature is fluid and cursive, with the first name "Michael" and last name "Reeves" clearly distinguishable.

Michael Reeves

Registered Landscape Architect #486

FRLA AILA

**QUALITY ASSURANCE**

Contact information

**MICHAEL REEVES LANDSCAPE ARCHITECT**

35 Darke Street  
TORRENS ACT 2607

Phone        02 6290 1728        0413403483

Email        **mreeves1@bigpond.net.au**

Quality assurance information

Report title:        Arborist Report – 110 Rossi Street Yass

Date:        23 May 2025

Prepared by:        Michael Reeves

Issue history

Issue Number	Issue Date	Details	Authorised
1	23 May 2025	Report	Mr



# ISA Basic Tree Risk Assessment Form

Client Yass Valley Council Date 23/5/2025 Time 10:30am  
 Address/Tree location 110 Rossi Street Yass Tree no. 1 Sheet 1 of 1  
 Tree species Melia azedarach dbh 1.0 Height 6m Crown spread dia. 12m  
 Assessor(s) Michael Reeves Time frame 1 Tools used —

## Target Assessment

Target number	Target description	Target zone			Occupancy rate 1 - rare 2 - occasional 3 - frequent 4 - constant	Practical to move target?	Restriction practical?
		Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	Adjacent power pole	✓	✓	✓	4	N	N
2	Footpath under canopy	✓	✓	✓	2	N	N
3	Road adjacent	✓	✓	✓	2	N	N
4							

## Site Factors

History of failures — Topography Flat ☐ Slope ☒ 30 % Aspect N  
 Site changes None ☒ Grade change ☐ Site clearing ☐ Changed soil hydrology ☐ Root cuts ☐ Describe Existing street tree  
 Soil conditions Limited volume ☐ Saturated ☐ Shallow ☐ Compacted ☐ Pavement over roots ☒ 60 % Describe Street tree  
 Prevailing wind direction NW Common weather Strong winds ☐ Ice ☐ Snow ☐ Heavy rain ☐ Describe Yass, NSW

## Tree Health and Species Profile

Vigor Low ☐ Normal ☒ High ☐ Foliage None (seasonal) ☐ None (dead) ☐ Normal 100 % Chlorotic — % Necrotic — %  
 Pests — Abiotic —  
 Species failure profile Branches ☐ Trunk ☐ Roots ☐ Describe —

## Load Factors

Wind exposure Protected ☐ Partial ☐ Full ☒ Wind funneling ☐ Relative crown size Small ☒ Medium ☐ Large ☐  
 Crown density Sparse ☐ Normal ☒ Dense ☐ Interior branches Few ☐ Normal ☒ Dense ☐ Vines/Mistletoe/Moss ☐ —  
 Recent or planned change in load factors —

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown ☒ LCR — % Cracks ☐ Lightning damage ☐  
 Dead twigs/branches ☐ — % overall Max. dia. — Codominant ☒ Included bark ☒  
 Broken/Hangers Number — Max. dia. — Weak attachments ☐ Cavity/Nest hole — % circ.  
 Over-extended branches ☒ Previous branch failures ☐ Similar branches present ☐  
 Pruning history Crown cleaned ☐ Thinned ☐ Raised ☐ Dead/Missing bark ☐ Cankers/Galls/Burls ☐ Sapwood damage/decay ☐  
 Reduced ☐ Topped ☒ Lion-tailed ☐ Conks ☐ Heartwood decay ☐  
 Flush cuts ☐ Other — Response growth —  
 Main concern(s) Canopy removed for power lines. Overextended branches

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☒  
 Likelihood of failure Improbable ☐ Possible ☐ Probable ☒ Imminent ☐

### — Trunk —

Dead/Missing bark ☐ Abnormal bark texture/color ☐  
 Codominant stems ☒ Included bark ☐ Cracks ☐  
 Sapwood damage/decay ☐ Cankers/Galls/Burls ☐ Sap ooze ☐  
 Lightning damage ☐ Heartwood decay ☐ Conks/Mushrooms ☐  
 Cavity/Nest hole — % circ. Depth — Poor taper ☐  
 Lean — ° Corrected? —  
 Response growth —  
 Main concern(s) Overextended branches

Load on defect N/A ☐ Minor ☐ Moderate ☐ Significant ☒  
 Likelihood of failure Improbable ☐ Possible ☐ Probable ☒ Imminent ☐

### — Roots and Root Collar —

Collar buried/Not visible ☐ Depth — Stem girdling ☐  
 Dead ☐ Decay ☐ Conks/Mushrooms ☐  
 Ooze ☐ Cavity ☐ — % circ.  
 Cracks ☐ Cut/Damaged roots ☐ Distance from trunk —  
 Root plate lifting ☐ Soil weakness ☐  
 Response growth —  
 Main concern(s) N/A

Load on defect N/A ☒ Minor ☐ Moderate ☐ Significant ☐  
 Likelihood of failure Improbable ☐ Possible ☐ Probable ☐ Imminent ☐



### Risk Categorization

Condition number	Tree part	Conditions of concern	Part size	Fall distance	Target number	Target protection	Likelihood																Consequences				Risk rating of part (from Matrix 2)		
							Failure				Impact				Failure & Impact (from Matrix 1)														
							Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant	Severe							
1	Canopy	Proximity to pole	L	3m		NIL	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	MOD		
2	Canopy	Overhead Lines					<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	MOD	
3	Canopy	Pedestrians on Footpath					<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	LOW	
4	Canopy	Parked Cars.					<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	High	

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impacting Target			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low

Notes, explanations, descriptions Shed tree with  
Centre of canopy removed for off power  
lines. Trees 3m from pole + transformer.  
Overextended branches.

Mitigation options None. Removal in favour of electrical  
infrastructure recommended

Residual risk \_\_\_\_\_  
 Residual risk \_\_\_\_\_  
 Residual risk \_\_\_\_\_  
 Residual risk \_\_\_\_\_

Overall tree risk rating Low ☐ Moderate ☒ High ☐ Extreme ☐

Work priority 1 ☐ 2 ☐ 3 ☐ 4 ☐

Overall residual risk Low ☐ Moderate ☒ High ☐ Extreme ☐

Recommended inspection interval \_\_\_\_\_

Data ☒ Final ☐ Preliminary Advanced assessment needed ☒ No ☐ Yes-Type/Reason \_\_\_\_\_

Inspection limitations ☒ None ☐ Visibility ☐ Access ☐ Vines ☐ Root collar buried Describe \_\_\_\_\_